



Limiting factors in regard to health condition of the attendees of the EPE Conference when visiting Latvenergo AS facilities at CHPP-2 and HPP

| No. | Possible health issues | Possible limiting factors | Notes |
|--------------------|------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| HPP, CHPP-2 | | | |
| 1. | Persons with reduced mobility who use technical aids (such as a wheelchair) to move around | 1) Problems with movement when passing through the checkpoint of the facility's production areas | It will not be possible to pass through the security checkpoint turnstile and use the stairs in a wheelchair. CHPP-2 has low access possibilities. <i>Moving around the machine hall at the HPP where the hydropower units are being reconstructed is limited.</i> |
| | | 2) Exposure to occupational risk factors (noise, vibration) | We provide the following personal protective equipment: a high visibility vest, a helmet and earplugs (if needed). |
| 2. | Persons with impaired vision | 1) Moving around the facility's production areas unaccompanied | <i>Moving around the machine hall at the HPP where the hydropower units are being reconstructed is limited.</i> |
| | | 2) Exposure to occupational risk factors (noise, vibration) | LE may provide personal protective equipment (a high visibility vest, a helmet and earplugs (if needed)). |
| 3. | Persons with impaired hearing | 1) Exposure to occupational risk factors (noise, vibration) | We provide the following personal protective equipment: a high visibility vest, a helmet and earplugs (if needed). |
| | | 2) Moving around the HPP production areas unaided | Safety signs must be obeyed at all times. <i>Moving around the machine hall at the HPP where the hydropower units are being reconstructed is limited.</i> |
| 4. | Persons with heart disorders, cardiac pacemakers or metal implants (devices that may be implanted in the human body for medical reasons) | 1) Possibility to move around the production areas, as EMF levels near power units may be increased | The duration of stay in the EMF exposure area (next to the operating power units/turbines) should be limited as far as possible. Safety signs must be obeyed at all times. <i>Moving around the machine hall at the HPP where the hydropower units are being reconstructed is limited.</i> |
| | | 2) Persons with active cardiac pacemakers or metal implants in the body are denied access to the operating power units at the facility |   <p style="font-size: small;"> Cilvēkiem, kuru ķermenī implantētas aktīvas sirdsdarbības stimulatora ierīces, piekļuve aizliegta! Cilvēkiem, kuru ķermenī ir metāla implanti, piekļuve aizliegta! </p> <p>Persons with active cardiac pacemakers implanted in the body are denied access! Persons with metal implants in the body are denied access!</p> |
| | | 3) Exposure to occupational risk factors (noise, vibration) | We provide the following personal protective equipment: a high visibility vest, a helmet and earplugs (if needed). |

For the visitors of Latvenergo AS facilities at CHPP-2 and HPP flat shoes are required.